













Ввод питания №1

Ввод питания №2



ABP-PRS-K-2-1-100-CHINT



- 1L1 ↔ 2T1 /5.0
- 3L2 ↔ 4T2 /5.1
- 5L3 ↔ 6T3 /5.1
- 53 ↔ 54 /5.6
- 61 ↔ 62 /5.6

- 1L1 ↔ 2T1 /5.2
- 3L2 ↔ 4T2 /5.2
- 5L3 ↔ 6T3 /5.2
- 53 ↔ 54 /5.6
- 61 ↔ 62 /5.6

| | |
|---------------|--|
| Инва. № подл. | |
| Подп. и дата | |

| | | | | |
|------|--------|---------|------|------|
| Ред. | Листов | № докум | Подп | Дата |
| | | | | |

Листов